

[Return to Vehicle \(/vehicle/details/5FNYF4H22BB077567/1432927/\)](/vehicle/details/5FNYF4H22BB077567/1432927/)

# CONDITION REPORT \*\*

Created: Jul 03, 2018  
Printed: July 19, 2018  
Auction Id: 263193  
5FNYF4H22BB077567  
  
TCAR RECOVERY AND REMARKETING SERVICES  
Contact: PATRICK  
Email: PATRICKDUNLEAVY@TCARINC.COM  
Phone: 518-881-0154 X 1939

## 2011 HONDA PILOT

WHITE Odometer:180,223


### DESCRIPTION

#### DRIVELINE


ENGINE **SEEMS OK** | BRAKES **SEEMS OK** | TRANSMISSION **SEEMS OK** | EXHAUST **SEEMS OK**

#### ISSUES & CLEANLINESS

INTERIOR **SEEMS OK** | ENGINE COMPARTMENT **SEEMS OK** | TRUNK/BED **SEEMS OK**



- 1. Roof **SEEMS OK**
- 2. Windshield **SEEMS OK**
- 3. Hood **SEEMS OK**
- 4. Grill **SEEMS OK**
- 5. F Bumper **SCRATCHED**
- 6. Mirrors **SEEMS OK**
- 7. F Lights **SEEMS OK**

**DRIVER'S SIDE**

T1. LF TIRE 5/32-2/32 - AVERAGE


13. LF FENDER SCRATCHED

14. LF DOOR SCRATCHED

15. LR DOOR SEEMS OK

16. LR QUARTER SEEMS OK

T2. LR TIRE 5/32 OR MORE - OK

**BACK**


8. R Window SEEMS OK

9. Trunk/TGate DING

10. Cargo Area SEEMS OK

11. R Bumper SCRATCHED

12. Tail Lights SEEMS OK

**PASSENGER'S SIDE**

T4. RR TIRE 5/32-2/32 - AVERAGE

17. RR QUARTER CREASED

18. RR DOOR SEEMS OK

19. RF DOOR SCRATCHED

20. RF FENDER CREASED

T3. RF TIRE 5/32-2/32 - AVERAGE





























\*\* This is an "AS IS" Auction with No Arbitration, the selling dealer makes every effort to list the vehicles condition accurately on their condition report and highlight the major flaws in their photos. Vehicle availability and description are subject to change without prior notice.

**It is ultimately the buyer's responsibility to review the car and judge the vehicles condition before bidding.**

Auction Simplified is not responsible for any errors or omissions contained on these pages